IASSC Certified Lean Six Sigma Yellow Belt

Six Sigma ICYB

Version Demo

Total Demo Questions: 6

Total Premium Questions: 150

Buy Premium PDF

QUESTION NO: 1

A single data point falling outside a Control Limit is most likely representative of _____.

A. Common-cause Variation

B. Special-cause Variation

C. Predictability

D. Non-normal data

ANSWER: A

QUESTION NO: 2

Which of the following is a method of expressing the concept that the outputs of a process are a function of all the inputs to the process?

A. $Y = f(Xn)$

B. RTY > 90%

C. Yield = Effort

D. Flow = Demand

ANSWER: A

QUESTION NO: 3

As a type of measurement error, Linearity describes the deviation of the measured value from the actual value.

A. True

B. False

ANSWER: B

QUESTION NO: 4

The following Business Case is constructed properly.

"During most of 2008 Division 16 experienced a 4.2% product return rate versus a target of nearly no returns. This costs the company a whole bunch of money.

A. True

B. False

ANSWER: B

QUESTION NO: 5

The Cost of Poor Quality (COPQ) is comprised of which two of the following? (Choose two.)

A. Tangible (Visible) Costs

B. Input Costs

C. Production

D. Hidden Costs

ANSWER: A B

QUESTION NO: 6

One of the primary benefits of your team working together to create an X-Y Diagram is that the data collected from this exercise is accurate and certain.

A. True

B. False

ANSWER: B